



1. Start a **Mechanical APDL Product Launcher**
2. Create a folder (for example: D:\FEM1) and select it (Browse...) or type the name of a folder in the field Working Directory (the folder will be created by the ANSYS program)
3. Define a Job Name (for example: file)
4. Run



Comments

It is strongly recommended to use a **Mechanical APDL Product Launcher** instead of double clicking on other icons or files.

Specification of a **Working Directory** is more important than the name of a **Job Name**.



What does the program want from me?

info about the active coordinate system

Output Window

